

## Model A-525

## **Pocket Sling Psychrometer**

## Replaceable Wick, Psychrometric Slide Chart Included



The Model A-525 Sling Psychrometer can be used to measure relative humidity by measuring the dry bulb and wet bulb temperatures. Wet bulb temperatures are measured by wetting a wick with distilled water on one of the thermometer legs of the psychrometer. On the other leg, the dry bulb temperature is measured. An included slide chart eliminates the need to use of graphs to determine the humidity. Replacement wicks are available as an accessory. Each sling psychrometer includes psychrometric graphs, psychormetric slide chart, and a carrying case.

**Model A-525**, Pocket type sling Psychrometer. Furnished complete with Psychrometric charts. Psychrometric slide chart, and carrying case

## **ACCESSORIES**

**A-527**, Replacement Wick for Psychrometer **A-530**, Psychrometric Slide Chart