


A76-SD Instrument Mounts



A76-SD Mount for Wind Sensors with sensors



Mount for A70-S&D Wind Sensors


Rating: Not Rated Yet

Price:


[Ask a question about this product](#)

Description

Model A76 Instrument Mounts



A76-HT Radiation Shield with
A70-HT/O Transmitter



A76-SD Mount with Wind Sensors



A76-I Mount with Pyranometer



A76-T10 Tripod Tower with X5 Cross Arms

TECHNICAL SPECIFICATION:

Sensor Exposure	
Wind Speed Mounting height:	Top of mast
Wind Direction Mounting height:	Top of mast
Air Temperature Mounting height:	4 - 5 feet (1 - 2 M) Exposure: North
Relative Humidity Mounting height:	4 - 5 feet (1 - 2 M) Exposure: North
Fuel Temperature Mounting height:	10 - 12 inches (25 - 30 cm) Exposure: South
Insolation Mounting height:	4 - 5 feet (1 - 2 M) Exposure: South

Reviews

There are yet no reviews for this product.